

WORKOVER PROCEDURE

WELL NAME: Ky Blue D30-32 **DATE:** 8/31/2016
LOCATION:
Qtr/Qtr: NE/SE Section: 25 Township: 3N Range: 65W
Footages: 2489' FSL & 212' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-34348

ENGINEER: Baxter Whittington 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 775' KB Elevation: 4807'
Surface Cmt: 371 sx GL Elevation: 4794'
Long St Csg: 4 1/2" 11.60# M-80 @ 7687' TD: 7697'
Long St Cmt: 665 sx PBTD: 7632'
Long St Date: 3/18/2012

Plug Back (Sand or CIBP): Tbg Tally @ 7632'
Perforation Interval (1): Nio Perforations 6816' - 6930'
Perforation Interval (2): Codell Perforations 7048' - 7062'
Perforation Interval (3): J Sand Perforations 7512' - 7572'
Tubing: 2-3/8" @ 7486' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: PR
COMMENTS: Plugging due to BH concerns

PROCEDURE: SEE COA ON APPROVED PROCEDURE

- 1) MIRU Workover rig, pump & tank.
- 2) Unland 2 3/8" tbg. POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7465', dump bail 2 sx of cement on top.
- 4) RIH w/ CIBP. Set CIBP @ 6770', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 54 sx balanced plug @ 5050' to cover Sussex (ETOC= 4350').
- 6) POOH to 2500' to pump 20 sk courtesy plug from 2500' - 2245'.
- 7) Unland casing. Cut casing off @ 890'. POOH with casing laying down on trailer.
- 8) RIH w/ workstring to pump 294 sx stub/shoe plug at 940'. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.