

REENTRY PROCEDURE

WELL NAME: PRINCE 3-29 DATE: 8/9/2016
 LOCATION: Qtr/Qtr: NENW Section: 29 Township: 9N Range: 58W
 COUNTY: WELD STATE: CO API #: 05-123-13945

ENGINEER: Hunter Dunham 7 Day Notice Sent:
 (Please notify Engineer of any major changes prior to work) Do not start operations until:
 Notice Expires:

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 11' - 258' KB Elevation: 4841
 Surface Cmt: 155 sks GL Elevation: 4840
 Long St Csg: 5 1/2" 15.5# 5860 - 6650 TD: 6656'
 Long St Cmt: 145 sks, TOC @ 5950' PBTD:
 Long St Date: 6/27/1988
 Plug Info (1) CIBP set @ 6020' w/ 3 sks of cmt
 Plug Info (2) 20 sk balanced cmt plug 1130'
 Plug Info (3) 26 sk cmt plug 270'
 Plug Info (4) 10 sk cmt plug at surface
 Tubing: Rods:
 Pump:
 Misc.: *Niobrara @ 5782', Deepest Water Well @ 695', Base Fox Hills @ 627', Base Upper Pierre @ 1449'*

WELL STATUS: Well abandoned 10/1/88

COMMENTS: Cap welded on surface

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging (TOC @ 220ft).
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 4000'
- 15) Circulate 2x hole volume (500bbl) to condition hole
- 16) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 17) PU and RIH with mule shoe and 2 7/8" tubing to 4000'.