

WORKOVER PROCEDURE

WELL NAME: Chesnut G22-20D **DATE:** 9/20/2016

LOCATION:
Qtr/Qtr: SENW Section: 22 Township: 4N Range: 65W
Footages: 2480 FNL & 2320 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-30286

ENGINEER: Jeanne Van Slambrouck 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8", J-55, 32# @ 569' KB Elevation: 4,764
Surface Cmt: 216 sx GL Elevation: 4,748
Long St Csg: 4-1/2", N-80, 11.60# @ 7,377' TD: 7,399
Long St Cmt: 708 sx PBTD: 7,331
Long St Date: 2/20/2010

Plug Back (Sand or CIBP): **sand**
Perforation Interval (1): Niobrara Perforations: 7,072' - 7,132'
Perforation Interval (2): Codell Perforations: 7,216' - 7,231'
Perforation Interval (3): _____
Tubing: 2-3/8", J-55, 4.70# @ 7,202' Rods: _____
Pump: _____
Misc.: **Bit Sub @ 7,202'**

PRODUCTION STATUS: Producing, 1.5 bopd and 55 mcf/d, 385# / 404#

COMMENTS: Uneconomic to do annular fill and STEM

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7,022', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring. Pump 25 sx balance plug across the Sussex from 4,150' to 4,450'.
- 5) Unland casing. Cut casing off @ 2,050'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring. Pump 100 sx stub plug where casing was pulled.
- 7) POOH to 670'. Pump 250 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.