

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2016

Submitted Date:

09/20/2016

Document Number:

674602794

FIELD INSPECTION FORM

Loc ID 307063 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10312
Name of Operator: PROSPECT ENERGY LLC
Address: 500 DALLAS STREET SUITE 1800
City: HOUSTON State: TX Zip: 77002

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Gracey, Cam		graceyservices@msn.com	
Smith, Sydney		ssmith@progressivepcs.net	
Martin, Dene		dmartin@memorialrd.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216721	WELL	PR	06/30/2011	OW	069-05134	MARTINEZ (MUDDY UNIT) 1	EG

General Comment:

[Followup engineering integrity inspection conducted on September 15th, 2016 in response to an initial form 19 spill report Doc #401054614 submitted to COGCC on 05/26/2016. See the flowline section of this report for details. Photo Uploaded.](#)

Inspected Facilities

Facility ID: 216721 Type: WELL API Number: 069-05134 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: No Age: 20+ Yrs Contents: Multiphase

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: Yes
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Internal corrosion led to the failure (hole) in the well site flowline near the Martinez 1 wellhead; Approximately 22' of damaged flowline pipe was cut out and replaced with new FBE coated material. The flowline repair has been completed; Excavations on well pad have been backfilled. Follow up pressure testing completed; Flowline pressure test result deemed satisfactory.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602794	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956922
674602795	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956906