

WORKOVER PROCEDURE

WELL NAME: Wells Ranch USX AA13-06 **DATE:** 9/22/2016
LOCATION:
Qtr/Qtr: SENW Section: 13 Township: 6N Range: 63W
Footages: 2088 FNL & 2134 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-26966

ENGINEER: Dustin Stevens 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:
Surface Csg: 8 5/8" 24# J-55 @ 568' KB Elevation: 4809'
Surface Cmt: 275 GL Elevation: 4796'
Long St Csg: 4 1/2 " 11.60 M-80 @ 6920' TD: 6928'
Long St Cmt: 730 PBTD: 6851'
Long St Date: 7/30/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6492'-6602'
Perforation Interval (2): Codell Perforations 6758'-6768'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 6711' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI
COMMENTS: _____

PROCEDURE:

- 1) Complete a Form 17
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6442', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 20 sx courtesy plug @ 2500' (top of plug 2200').
- 6) Unland casing (if able). Cut casing off (in slips if unable to unland) @ 668'. POOH w/ casing laying down on trailer.
- 7) RIH w/ workstring to 668'. Pump 225 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.