

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2016

Submitted Date:

09/23/2016

Document Number:

671000440

FIELD INSPECTION FORM

Loc ID 416887 Inspector Name: LUJAN, CARLOS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Kasten, Matt		Matthew.Kasten@encana.com	Environmental
Rider, Lindsey		Lindsey.Rider@encana.com	Manager, Field Environmental
Middleton, Brett		Brett.Middleton@encana.com	Environmental Specialist

General Comment:

On Site with Brett Middleton from Encana. Environmental Inspection conducted on the O1 EB Encana pad after an unidentified person left a condensate tank valve open. Fluid was mostly contained within the lined secondary containment, however an unknown volume of condensate leaked outside of the containment. Staining was observed on the south side of the tank battery, within the pad. Fluid within the secondary containment was removed via vac truck.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Unknown amount of condensate was spilled within the secondary containment and subsequently removed via vac truck. However, the containment liner was compromised and condensate leaked outside of the secondary containment but within the pad. Encana submitted spill report doc #401108134 (Spill/Release Point ID #447773).

Corrective Action: Submit a Form 27 Site Assessment and Remediation Work Plan.

Date: 10/14/2016

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Follow-up environmental inspection(s) will be conducted as excavation and remediation work progresses. Please notify the COGCC 48 hours in advance of significant work to be conducted onsite, such as excavation, drilling boreholes, etc.	lujanc	09/23/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000441	Encana O1 EB pad. Tank valve left open	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960622
671000442	Encana O1 EB pad. Condensate leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960623
671000443	Encana O1 EB pad. Secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960624
671000444	Encana O1 EB pad. Compromised liner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960625