

WORKOVER PROCEDURE

WELL NAME: TENNYSON 34-04 **DATE:** 9/24/2016
LOCATION:
Qtr/Qtr: NW/NW Section: 34 Township: 6N Range: 66W
Footages: 573 FNL & 664 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-17130

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, grade? @495' KB Elevation: 4707'
Surface Cmt: 390 sx GL Elevation: 4696'
Long St Csg: 2 3/8" 4.70#, WC50 @ 7322' TD: 7325'
Long St Cmt: 210 sx PBTD: 7296'
Long St Date: 7/1/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6904' - 7106'
Perforation Interval (2): Codell Perforations 7195' - 7205'
Perforation Interval (3): _____
Tubing: Wellbore diagram shows no tbg d/h Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently S/I
COMMENTS: Wellhead is not tree'ed and no tubing D/H

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/ CIBP. Set CIBP @ 6854', dump bail 2 sx of cement on top.
- 3) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 4) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 5) POOH w/ workstring to 750'. Pump 296 sx shoe plug. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. RDMOL.