

**WORKOVER PROCEDURE**

**WELL NAME:** Monfort Gilcrest K08-15 **DATE:** 9/30/2016

**LOCATION:**  
Qtr/Qtr: SW/SE Section: 8 Township: 4N Range: 66W  
Footages: 660 FSL & 2080 FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-18958

**ENGINEER:** JOSH CHEBUL **7 Day Notice Sent:** \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** \_\_\_\_\_  
**Notice Expires:** \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8" 24# @ 572' KB Elevation: 4710'  
Surface Cmt: 350 sx GL Elevation: 4700'  
Long St Csg: 3-1/2" 9.3# @ 7387' TD: 7406'  
Long St Cmt: 905 sx PBTD: 7381'  
Long St Date: 8/26/1996

Plug Back (Sand or CIBP): Sand  
Perforation Interval (1): Codell Perforations 7,219'-7,234'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2-1/16" 3.25# J-55 @ 7198' Rods: N/A  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** Producing

**COMMENTS:** Wellhead leak detected; can't afford repair cost

**PROCEDURE:**

- 1) Confirm bradenhead Form 17 has been performed within the last year and that a sample has been taken, if required. If a Form 17 has not been performed, rig foreman to perform Form 17 and recover any necessary samples; direct sample to DIG/Precision contact for analysis.
- 2) MIRU workover rig, pump & tank.
- 3) POOH w/ 2-1/16" tbg and stand back.
- 4) RU WL. RIH w/ CIBP (note casing is 3-1/2"). Set CIBP @ 7169'. POOH.
- 5) RIH w/ tubing. Tag CIBP and pump 20 sx of cement on top of it to cover Niobrara Fm by 100'. POOH. Top of plug: 6698'.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 7) RIH w/ tubing to pump 170 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. Bottom of plug: 2500'. Top of plug: 2142'. (assumes 10" hole)
- 8) POOH w/ tubing to 710'. Pump 340 sx shoe plug (assumes 10" hole). Cement to surface. Bottom of plug: 710'. Top of plug: surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. RDMOL.