

WORKOVER PROCEDURE

WELL NAME: UPRC 03-1116 **DATE:** 10/5/2016

LOCATION:
Qtr/Qtr: NE/SW Section: 3 Township: 4N Range: 66W
Footages: 2349 FSL & 1657 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-18024

ENGINEER: Jeanne Van Slambrouck **7 Day Notice Sent:** _____
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 448' KB Elevation: 4707'
Surface Cmt: 367 sx GL Elevation: 4693'
Long St Csg: 3 1/2" 7.7#, B-70 @ 7363' TD: 7389'
Long St Cmt: 197 sx PBTD: 7283'
Long St Date: 3/6/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6872' - 7010'
Perforation Interval (2): Codell Perforations 7187' - 7200'
Perforation Interval (3): _____
Perforation Interval (4): _____
Tubing: 2 1/16" 3.25# J-55 tbg @ 7180' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: Provide 48 hr notice of plugging MIRU via electronic form 42.
Abandon flowlines as per Rule 1103. File electronic form 42 once abandonment completed.

PROCEDURE:

- 1) Prior to plugging operations, perform a bradenhead test.
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2 1/16" tbg and lay down.
- 4) RIH w/ workstring w/ tubing-set CIBP. Set CIBP @ 6822', dump bail 2 sx of cement on top.
- 5) POOH w/ workstring to 4070' and pump 20 sx balance plug across sussex.
- 6) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 550'. Pump 215 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.