

WORKOVER PROCEDURE

WELL NAME: BIERIG 01-26B **DATE:** 10/7/2016

LOCATION: Qtr/Qtr: NE/NE Section: 26 Township: 5N Range: 66W

Footages: 480 FNL & 690 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-24918

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, grade? @ 547' KB Elevation: 4785'
Surface Cmt: 400 sx GL Elevation: 4775'
Long St Csg: 4 1/2" 11.60#, grade? @ 7816' TD: 7833'
Long St Cmt: 550 sx PBTD: 7813'
Long St Date: 11/23/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6960' - 7096'
Perforation Interval (2): Codell Perforations 7212' - 7222'
Perforation Interval (3): _____
Tubing: Currently no tbg d/h Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently S/I

COMMENTS: _____

PROCEDURE:

- 1) Verify Form 17 bradenhead test has been completed prior to MIRU
- 2) MIRU Workover rig, pump & tank.
- 3) If there is tbg d/h, POOH w/ tbg and lay down, otherwise go to step #4.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6910', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 20 sx csg plug @ 2500' (to 2336')
- 6) Unland casing. Cut casing off @ approx. 1980'. POOH w/ casing laying down on trailer.
- 7) RIH w/workstring to 2030' and pump 100 sx stub plug.
- 8) POOH w/ workstring to 647'. Pump 240 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. RDMOL.