



photo 1: Facing southwest along the main access road. Erosion issues have been corrected.



photo 2: Facing southeast along the main access road. Erosion issues have been corrected.



photo 3: Rock rip/rap has been installed along the road.



photo 4: Facing southwest along the main access road. Erosion issues have been corrected.
Note: Stormwater flow along the access road should be de-energized by installing check dams, ect..



photo 5: The main road switches back to the northeast at this point. Erosion issues have been corrected.



photo 6: Facing southeast along the main access road. Erosion issues have been corrected.



photo 7: A culvert has been installed where water was flowing across the road. Outlet protect has been placed at the culvert.



photo 8: Facing southeast at the location. The location has been seeded and hydro-mulched.



photo 9: Facing southwest toward the cut slope.



photo 10: Facing west toward the cut slope which has been seeded and hydro-mulched.



photo 11: Facing north along the fill slope.



photo 12: Facing east off the fill slope.