

PLUG and ABANDONMENT PROCEDURE

SARCHET 33-15L

Step	Description of Work
------	---------------------

- | | |
|-----|---|
| 1. | Provide 48 hour notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.). Notify Automation Removal Group at least 24 hours prior to rig move. Isolate production equipment, and remove any automation prior to rig MIRU. |
| 2. | MIRU Slickline. Gyro ran 11/18/2014. Record tag depth in Open Wells. RD slickline. |
| 3. | Prepare location for base beam equipped rig. Install perimeter fence as needed. |
| 4. | Check and record bradenhead pressure. If bradenhead valve is not accessible, re-plumb so that valve is above GL. Blow down bradenhead and re-check pressure the next day. Repeat until pressure stays at 0 psi. |
| 5. | MIRU WO rig. Spot in min 25 jts of 2.06" 3.25# J-55, tbg. Kill well as necessary using clean fresh water with biocide. ND WH. NU BOP. |
| 6. | TOOH. SB all 2.06" tbg. |
| 7. | PU and TIH with (3.5", 7.7#) bit and scraper on 2.06" tbg to 7310'. TOOH. SB all 2.06" tbg. LD and Bit and Scraper. |
| 8. | RU WL. PU and RIH with (3.5", 7.7#) CIBP and set at +/- 7300' to abandon the Codell perms. POOH. |
| 9. | Well does not have CBL. PU and RIH w/ CCL-GR-CBL-VDL. Run log from 7300' to surface and send results to engineering. POOH. RD WL. Contact Engineering to confirm adequate coverage. |
| 10. | TIH with 2.06" tbg while hydrotesting to 3000 psi to 7300'. Circulate all gas from well. PT CIBP to 3000 psi for 15 minutes. (Going to use 3.5" as work string eventually, that is why we PT to 3000 psi) |
| 11. | <u>RU cementers.</u> Pump Niobrara Balance Plug: Pump 25 sxs (39 cf) 15.8 ppg & 1.55 cf/sk. Volume based on 590' inside 3.5" production casing. Cement will be from 7300' – 6710'. RD cementers. |
| 12. | Slowly pull out of the cement and PUH to 6500'. Reverse circulate tubing clean to ensure no cement is left in the tubing. TOOH and LD all 2.06" tbg. |
| 13. | RU WL. RIH and jet cut 3.5" casing at 4875'. TOOH. RD WL. |
| 14. | Circulate with fresh water containing biocide to remove any gas. |
| 15. | ND BOP. ND TH. Un-land casing using a casing spear, not a lifting sub. Max pull shall be 50,000# over string weight. If unable to unland, contact Engineering. |
| 16. | Install BOP on casing head with 3.5" pipe rams. |
| 17. | Raise 3.5" casing to floor. |
| 18. | Establish circulation to surface with biocide treated fresh water at least bottoms up. If you cannot circulate up surface casing call engineering. |
| 19. | <u>RU Cementers.</u> Pump Sussex Balance Plug: Pump 10 bbls sodium silicate followed by 5 bbls fresh water spacer. 400 sx (472 cf) w/ Polyflake, 15.8 ppg & 1.18 cf/sk. Volume is based on 877' in 9" OH w/ 20% excess factor. Cement will be from 4875' – 3998'. |
| 20. | Slowly pull out of the cement and PUH to 3700'. Circulate to ensure no cement is left in the tbg. |

Engineer: Sterling Metzger

Cell: 330-605-2231

PLUG and ABANDONMENT PROCEDURE

SARCHET 33-15L

21. WOC per cement company recommendation. TIH and tag cement. Cement top needs to be at or above 3998' (200' above the SX top at 4198'). Call Engineering if tag is lower than 3998'.
22. TOOH to 1090' w/ 3.5" csg, LD remaining tbg.
23. Establish circulation with biocide treated fresh water and pump one hole volume (130 bbls). Pump 10 bbls (min) SAPP, followed by 5 bbls fresh water spacer.
24. RU Cementers. **Pump Stub Plug:** 285 sxs (331 cf) 0.25 lb/sk Polyflake, 15.8 ppg & 1.16 cf/sk (455' in 7.88 bit size w/ 60% excess factor, and 200' in 8-5/8" surface casing with no excess). The plug will cover 1090' – 585' RD cementers. Notify Engineering if circulation is ever lost during job.
25. Slowly pull out of the cement and PUH to 100'. Reverse Circulate using biocide treated fresh water, to ensure the tubing is clean. TOOH. LD all csg.
26. RU WL. RIH 8-5/8" 23# CIBP to 80'. RDMO WL and WO rig.
27. Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hours of completion of the job.
28. Supervisor submit paper copies of all invoices, logs, and reports to Evans Engineering Specialist.
29. Excavation crew to notify One Call to clear excavation area around wellhead and for flow lines.
30. Capping crew will set and secure night cap on 8 5/8" casing head, restrain the casing head, pressure test CIBP to 500 psi with hydrotest pump, then remove night cap and casing head restraints.
31. Excavate hole around surface casing enough to allow welder to cut casing a minimum 5' below ground level.
32. Welder cut casing minimum 5' below ground level.
33. Fill casing to surface using 4500 psi compressive strength cement (NO gravel).
34. Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
35. Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
36. Properly abandon flow lines per Rule 1103. File electronic Form 42 once abandonment is complete.
37. Back fill hole with fill. Clean location, and level.
38. Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed.