

WORKOVER PROCEDURE

WELL NAME: WILHITE 30-31 DATE: 10/24/2016

LOCATION: Qtr/Qtr: NESW Section: 30 Township: 7N Range: 64W

Footages: 2170 FSL & 1807 FWL

COUNTY: WELD STATE: CO API #: 05-123-24806

ENGINEER: JASON LEHMAN 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 687' KB Elevation: 4873'
Surface Cmt: 350 sx GL Elevation: 4861'
Long St Csg: 4 1/2" 11.6# @ 7279' TD: 7317'
Long St Cmt: 135 sx PBDT: 7274'
Long St Date: 10/17/2007

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7151' - 7164'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 tbg @ 7167' Rods:
Pump:
Misc.: Nio top @ ~6831'

PRODUCTION STATUS: SI for emissions compliance

COMMENTS: Codell only well

PROCEDURE:

- 1) Confirm that a Form 42 was filed, Form 17 has been performed and sample taken (only if required). If a Form 17 has not been performed, rig foreman to perform Form 17 and necessary sampling if required.
2) MIRU Workover rig, pump & tank.
3) POOH w/ 2 3/8" tbg and lay down.
4) RU WL. RIH w/ CIBP. Set CIBP @ 7101', dump bail 2 sx of cement on top.
5) RIH w/ workstring to 7101'. Pump 30 sx plug on top of CIBP. If circulation is maintained, no need to tag plug.
6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
8) POOH w/ workstring to 755'. Pump 290 sx shoe plug. Cement to surface.
9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
10) Cut surface casing off 6'-8' below ground.
11) Clean up location. Reclaim location. RDMO.