

WORKOVER PROCEDURE

WELL NAME: EIFERT 11-42 DATE: 10/5/2016

LOCATION: Qtr/Qtr: NW/SE Section: 11 Township: 6N Range: 65W

Footages: 1919 FSL & 1808 FEL

COUNTY: WELD STATE: CO API #: 05-123-21645

ENGINEER: JOHN HATCH 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, J-55 @ 450' KB Elevation: 4793' Surface Cmt: 250 sx GL Elevation: 4783' Long St Csg: 4 1/2" 11.60#, M-80 @ 7283' TD: 7297' Long St Cmt: 165 sx PBTD: 7246' Long St Date: 9/10/2003

Plug Back (Sand or CIBP): Perforation Interval (1): Niobrara Perforations 6955' - 6984' Perforation Interval (2): Codell Perforations 7145' - 7160' Perforation Interval (3): Tubing: Rods: Pump: Misc.:

PRODUCTION STATUS: Well is currently producing but is uneconomic

COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6905', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 550'. Pump 206 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. RDMOL.