

WORKOVER PROCEDURE

WELL NAME: CARLSON 14-2 **DATE:** 10/5/2016
LOCATION:
Qtr/Qtr: SW/NE Section: 14 Township: 6N Range: 66W
Footages: 1980 FNL & 1980 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-10850

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36.0#, grade? @ 456' KB Elevation: 4801
Surface Cmt: 360 sx GL Elevation: 4790'
Long St Csg: 5 1/2" 17.0#, K-55 @ 7314' TD: 7320'
Long St Cmt: 200 sx PBTD: 7252'
Long St Date: 10/19/1982

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7218' - 7232'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 7/8" 6.50#, grade? @ 7137' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Well is currently producing but is uneconomic
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7168', pump 41 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 556'. Pump 247 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.