

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 401142648			
Date Received:			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>69175</u>	Contact Name: <u>Jenifer Hakkarinen</u>
Name of Operator: <u>PDC ENERGY INC</u>	Phone: <u>(303) 8605800</u>
Address: <u>1775 SHERMAN STREET - STE 3000</u>	Fax: _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>	Email: <u>Jenifer.Hakkarinen@pdce.com</u>

For "Intent" 24 hour notice required, Name: _____ Tel: _____
COGCC contact: Email: _____

API Number <u>05-123-12914-00</u>	Well Number: <u>10-2</u>
Well Name: <u>SPAUR</u>	
Location: QtrQtr: <u>SESW</u> Section: <u>10</u> Township: <u>4N</u> Range: <u>67W</u> Meridian: <u>6</u>	
County: <u>WELD</u> Federal, Indian or State Lease Number: <u>68106</u>	
Field Name: <u>WATTENBERG</u> Field Number: <u>90750</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.321390 Longitude: -104.879310

GPS Data:
 Date of Measurement: 04/02/2008 PDOP Reading: 2.5 GPS Instrument Operator's Name: Holly L. Tracy

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA-CODELL	6995	7225	01/04/2016	B PLUG CEMENT TOP	6945

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	300	250	300	0	VISU
1ST	7+7/8	4+1/2	11.6	7,306	370	7,306	5,786	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6945 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 215 sacks half in. half out surface casing from 565 ft. to 0 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 450 ft. of 4+1/5 inch casing Plugging Date: 01/04/2016

*Wireline Contractor: Nabors *Cementing Contractor: Sanjel

Type of Cement and Additives Used: 15.8 PPG Class G Cement

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Spaur #10-2 (05-123-12914)/Plugging Procedure
Producing formation: Niobrara/Codell
Existing Perforations: Niobrara/Codell - 6,995'-7,225'
TD: 7,306' PBTD: 7,262'
Surface Casing: 8 5/8" 24# @ 300' w/ 250 sks cmt.
Production Casing: 4 1/2" 11.6# @ 7306' w/ 370 sks cmt (TOC at 5,776').

Procedure:

1. MIRU pulling unit.
2. Blow down to tanks. Load with fluid to kill well.
4. Rig up wireline. RIH with CIBP. Set CIBP at 6,945'.
5. Load dump bailer with 2sx of 15.8#/gal CI G cement. TIH with dump bailer and spot on top of CIBP.
6. RIH w/ casing cutter and cut casing at 450'. Pull casing out of hole.
7. TIH with workstring to 565'. Circulate and condition well in preparation to pump cement stub plug.
8. RU cementers. Mix and pump 215 sx of 15.8#/gal CL G cement.
10. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jenfier Hakkarinen

Title: Reg Tech Date: _____ Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

Attachment Check List

Att Doc Num

Name

401142649	CEMENT JOB SUMMARY
401142651	WIRELINE JOB SUMMARY
401142654	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)