

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2016

Submitted Date:

12/01/2016

Document Number:

685301886**FIELD INSPECTION FORM**
 Loc ID 334326 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258792	WELL	PR	12/19/2000	GW	067-08379	SIMON LAND & CATTLE 21U-1R 2	PR
294772	WELL	PR	02/29/2008	GW	067-09501	SIMON LAND & CATTLE 21U-1R 4	PR

General Comment:

[This was a follow-up inspection. See Stormwater Section for additional details. See link at end of report for path to downloadable pictures.](#)

Inspected FacilitiesFacility ID: 258792 Type: WELL API Number: 067-08379 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 294772 Type: WELL API Number: 067-09501 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Fail	Gravel	Pass			

Comment: W side of location has erosion channel cutting into the fill slope. Repair that was made was not sufficient to control erosion. New channel has already carried material down fill slope creating erosion channel.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to 1002.f guidance document for further details.

Date: 01/04/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301891	Sideview of channel looking NE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016997
685301892	Erosion channel looking down fill slope	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016998
685301893	Bottom of fill slope material deposit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016999