

WORKOVER PROCEDURE

WELL NAME: Bashor State AA16-11 **DATE:** 12/7/2016

LOCATION:
Qtr/Qtr: NE/SW Section: 16 Township: 6N Range: 63W
Footages: 1980' FSL & 1980' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-26126

ENGINEER: Dustin Stevens **7 Day Notice Sent:** _____
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 747' KB Elevation: 4693'
Surface Cmt: 290 GL Elevation: 4681'
Long St Csg: 4 1/2" 11.60 M-80 @ 6883' TD: 7196'
Long St Cmt: 400 PBTD: 6833'
Long St Date: 8/19/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6468' - 6584'
Perforation Interval (2): Codell Perforations 6744'-6754'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 6720' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI
COMMENTS: _____

PROCEDURE:

- 1) Perform Form 17
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6418', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 20 sx courtesy plug @ 2500' (top of plug 2200').
- 6) Unland casing (if able). Cut casing off (in slips if unable to unland) @ 847'. POOH w/ casing laying down on trailer.
- 7) RIH w/ workstring to 897'. Pump 265 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.