

## WORKOVER PROCEDURE

**WELL NAME:** Trump A13-09 **DATE:** 1/5/2017  
**LOCATION:**  
Qtr/Qtr: NESE Section: 13 Township: 6N Range: 64W  
Footages: 1980 FSL & 660 FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-24394

**ENGINEER:** Brian Ulmer 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8", J-55, 24# @ 494' KB Elevation: 4,662  
Surface Cmt: 279 sx GL Elevation: 4,650  
Long St Csg: 4-1/2", M-80, 11.60# @ 6,952' TD: 6,961  
Long St Cmt: 1010 sx PBTD: 6,961  
Long St Date: 3/19/2007

Plug Back (Sand or CIBP): **Sand**  
Perforation Interval (1): Niobrara Perforations: 6,502' - 6632'  
Perforation Interval (2): Codell Perforations: 6,785' - 6,797'  
Perforation Interval (3):  
Tubing: 2-3/8", J-55, 4.70# @ 6766' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** Frac'd into by Colt HZ wells. SI for STEM.  
**COMMENTS:** Base of Fox Hills - 344'. Deepest water well within 1 mi - 400'.

### PROCEDURE:

- 1) Ensure Form 17 has been performed.
- 2) MIRU Workover rig, pump & tank.
- 3) Roll hole of oil and gas and then POOH w/ 2-3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6,452', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off @ 1682'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 10 bbls mud flush before cement followed by 100 sx stub plug where csg was pulled. Plug should extend from at least 1682' to 1482'. If maintain circulation, no need to tag plug.
- 7) POOH to 594'. Pump 10 bbls mud flush before cement followed by 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.