

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/20/2017
Submitted Date:
01/20/2017
Document Number:
682401719

FIELD INSPECTION FORM

Loc ID 436885 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: BARRETT CORPORATION* BILL
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		COGCC_FIR@billbarrettcop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436884	WELL	DG	12/16/2016	LO	123-39313	Ruh 6-62-11-0857B2	RI
436886	WELL	DG	12/15/2016	LO	123-39314	Ruh 6-62-11-0659B2	RI
436887	WELL	DG	12/14/2016	LO	123-39315	RUH 6-62-11-0560B2	RI
436888	WELL	DG	12/16/2016	LO	123-39316	Ruh 6-62-11-0758B2	RI

General Comment:

This is a follow up stormwater inspection to the previous FIR Document #682401690 that was last inspected on January 10, 2017. COGCC staff contacted and communicated to the Operator on January 20, 2017 that sufficient stormwater BMPs were required and this would be a 48-hour corrective action. It should be noted that drilling operations are underway and final BMPs have not been installed.

COGCC staff contacted and communicated to the Operator on the previous inspection that stormwater BMPs appeared sufficient for initial construction but BMPs would need more work as the location is being constructed. Ditch and berm BMP would be insufficient by itself and would require additional final BMPs to prevent sediment laden storm runoff from leaving location. BMP appears to be in the same condition as the previous inspection on January 10, 2017.

Location Construction

Location ID: 436885 CDP: _____

Comment: Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, or a minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	No		

Comments: Erosion BMPs:
 Other BMPs:

Corrective Action: Date: 01/22/2017

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs:
 Other BMPs:

Corrective Action: Date: 01/22/2017

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 436884 Type: WELL API Number: 123-39313 Status: DG Insp. Status: RIFacility ID: 436886 Type: WELL API Number: 123-39314 Status: DG Insp. Status: RIFacility ID: 436887 Type: WELL API Number: 123-39315 Status: DG Insp. Status: RIFacility ID: 436888 Type: WELL API Number: 123-39316 Status: DG Insp. Status: RI**COGCC Comments**

Comment	User	Date
BMPs should remain in place and in proper functioning condition until the pad reaches final reclamation.	binschusc	01/20/2017
If the Operator believes sufficient BMPs are currently in-place, then provide construction calculations from the site specific stormwater plan demonstrating that the current BMPs are sufficient to prevent sediment laden storm runoff from leaving location.	binschusc	01/20/2017
Refer to attached inspection photos in Document #682401721.	binschusc	01/20/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401721	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056434