

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/20/2017

Submitted Date:

01/20/2017

Document Number:

682401719**FIELD INSPECTION FORM**Loc ID 436885 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION\* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		COGCC_FIR@billbarrettcop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436884	WELL	DG	12/16/2016	LO	123-39313	Ruh 6-62-11-0857B2	RI
436886	WELL	DG	12/15/2016	LO	123-39314	Ruh 6-62-11-0659B2	RI
436887	WELL	DG	12/14/2016	LO	123-39315	RUH 6-62-11-0560B2	RI
436888	WELL	DG	12/16/2016	LO	123-39316	Ruh 6-62-11-0758B2	RI

**General Comment:**

This is a follow up stormwater inspection to the previous FIR Document #682401690 that was last inspected on January 10, 2017. COGCC staff contacted and communicated to the Operator on January 20, 2017 that sufficient stormwater BMPs were required and this would be a 48-hour corrective action. It should be noted that drilling operations are underway and final BMPs have not been installed.

COGCC staff contacted and communicated to the Operator on the previous inspection that stormwater BMPs appeared sufficient for initial construction but BMPs would need more work as the location is being constructed. Ditch and berm BMP would be insufficient by itself and would require additional final BMPs to prevent sediment laden storm runoff from leaving location. BMP appears to be in the same condition as the previous inspection on January 10, 2017.

**Location Construction**Location ID: 436885 CDP: \_\_\_\_\_

Comment: Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, or a minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
BERMS	No		

Comments: Erosion BMPs: **Either no, or a minimal unconsolidated berm.**

Other BMPs:

Corrective Action: **Install sufficient BMP(s) in accordance with good engineering practices per Rule 1002.f. by corrective action date of January 22, 2017.**

Date: 01/22/2017

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: **Swallow ditch installed around perimeter of location, even a ditch dug to proper depth would be insufficient by itself.**

Other BMPs:

Corrective Action: **Install sufficient BMP(s) in accordance with good engineering practices per Rule 1002.f. by corrective action date of January 22, 2017.**

Date: 01/22/2017

**Comment:** **Final BMPs should be installed since drilling operations have already commenced.****Corrective Action:****Date:****On Site Inspection (305):**Surface Owner Contact Information:Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_Operator Rep. Contact Information:Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>436884</u>	Type: <u>WELL</u>	API Number: <u>123-39313</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436886</u>	Type: <u>WELL</u>	API Number: <u>123-39314</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436887</u>	Type: <u>WELL</u>	API Number: <u>123-39315</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436888</u>	Type: <u>WELL</u>	API Number: <u>123-39316</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401721.</a>	binschusc	01/20/2017
<a href="#">If the Operator believes sufficient BMPs are currently in-place, then provide construction calculations from the site specific stormwater plan demonstrating that the current BMPs are sufficient to prevent sediment laden storm runoff from leaving location.</a>	binschusc	01/20/2017
<a href="#">BMPs should remain in place and in proper functioning condition until the pad reaches final reclamation.</a>	binschusc	01/20/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401190562	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056436</a>
682401721	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056434">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056434</a>