

Inspection Photos

02/22/2017

Operator: Whiting O&G #96155

Location ID: 444459

Inspection Doc. Number: 682501698

County, CO

Section TS RW

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 1: Photo taken from the location on the north end of the location, facing east. Photos 1-4 provide overview of location.



Photo 2: Photo taken from the location on the north end of the location, facing southeast. Photos 1-4 provide overview of location.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 3: Photo taken from the location on the north end of the location, facing southwest. Photos 1-4 provide overview of location.



Photo 4: Photo taken from the location on the north end of the location, facing west. Photos 1-4 provide overview of location.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 5: Photo taken from the location entrance on the north end of the location, facing west. Photo shows vehicle tracking BMP (cattle guard) and culvert with armor.



Photo 6: Photo taken from the access road adjacent to the location entrance on the north end of the location. Photo shows stormwater control ditch at access road has been filled with soil, and is no longer in proper functioning conduction.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 7: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater and sediment control ditch along northern perimeter of location.



Photo 8: Photo taken from the northwest corner of the location, facing south. Photo shows stormwater and sediment control ditch along northern perimeter of location

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 9: Photo taken from the west end of the location. Photo of sediment trap used as a stormwater and sediment control BMP. Sediment trap does not have sufficient inlet and outlet protection. Also appears that outlet of trap is higher in elevation than the stormwater ditch and the constructed location.



Photo 10: Photo taken from the west end of the location, facing south. Photo shows what appears to be a "spill way" constructed adjacent to the stormwater ditch. "Spill way" appears to have been seeded and stabilized with crimped straw.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 11: Photo taken from the southwest corner of the location, facing north. Photo shows ditch and “spill way” on west end of location used as stormwater and sediment control BMPs



Photo 12: Photo taken from the southwest corner of the location, facing east. Photo shows stormwater control ditch along southern perimeter of the location.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 13: Photo taken from the southwest corner of the location. Photo shows stormwater and sediment control trap. Sediment trap does not have sufficient inlet and outlet protection.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 14: Photo taken from the southeast corner of the location, facing west. Photo shows stormwater control ditch along southern perimeter of the location.



Photo 15: Photo taken from the southeast corner of the location, facing north. Photo shows stormwater control ditch along eastern perimeter of the location. Photo also shows topsoil berm. Topsoil appears to have been seeded and crimped to stabilize soil.

Inspection Photos
Operator: Whiting O&G #96155
Location ID: 444459



Photo 16: Photo taken from the northeast corner of the location, facing south. Photo shows stormwater control ditch along eastern perimeter of the location. Photo also shows topsoil berm. Topsoil appears to have been seeded and crimped to stabilize soil.



Photo 17: Photo taken from the northeast corner of the location, facing west. Photo shows stormwater control ditch along eastern perimeter of the location.