

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/28/2017

Submitted Date:

03/28/2017

Document Number:

674901558**FIELD INSPECTION FORM**
 Loc ID 306757 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263129	WELL	PR	11/03/2015	GW	067-08707	FC LEIDY 001 2	EI

General Comment:

On March 28, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP FC Leidy 001 #2. For the most recent field inspection report for this facility, please refer to document #685300372. BP representative Julie Best was on site during this field inspection. This site visit was the result of a reported release along a pipeline ROW. The fluids reported by a passerby along the access road have been determined to be surface water run-off.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, meter run, telemetry, and PBV.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around well head and pump jack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric power supply		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment: Electric			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Telemetry			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.135833,-107.811850	
Comment: Paint is peeling off of top of tank.						
Corrective Action:					Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Waddles	Pass					
Compaction	Pass	Culverts	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On March 28, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP FC Leidy 001 #2. For the most recent field inspection report for this facility, please refer to document #685300372. BP representative Julie Best was on site during this field inspection. This site visit was the result of a reported release along a pipeline ROW. The fluids reported by a passerby along the access road have been determined to be surface water run-off.</p> <p>A release was reported to the operator on Saturday March 25, 2017. BP representatives notified COGCC that same day. A pool of standing water was noted by a passerby along the access road. The operator shut in the gathering line. Containment structures were constructed to stop the flow. The section of gathering line was reportedly pressure tested to 80 psi by the operator on 3/27/17. During this pressure test, no bubbles were observed in the pooled areas. BP representatives used hand held field conductivity meters to test the pooled water, the inflow that was discovered uphill, and the produced water from the FC Leidy 001 #2. The EC of the inflow water and pooled water was reported at approximately 1.5 mmhos/cm while the production water was reported at approximately 7 mmhos/cm. Upon further investigation the pooled water was determined to be surface water run-off, and not a produced water release. Surface water originating further up a drainage pools in a low lying area near the road. The operator also notified the CDPHE and La Plata County officials regarding the potential release.</p>	hughesj	03/28/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901559	PBV with paint peeling off.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110886
674901560	Earthen dam created to contain water.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110887
674901561	Earthen dike created to contain water.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110888
674901562	Close up of containment area.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110889
674901563	Source area of surface water.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110890
674901564	Proximity of location to the Florida River.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110891