

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/05/2017

Document Number:

682401965

FIELD INSPECTION FORM

Loc ID 159489 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		EHSRC@bonanzacrk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440780	WELL	PR	08/01/2015	OW	123-41116	State Crow Valley 41-21-20XRLNB	RI

General Comment:

This is a follow up stormwater inspection to FIR Document #682401747 and in response to FIRR Document #401213467 stating that corrective actions have been performed.

Inspected Facilities

Facility ID: 440780 Type: WELL API Number: 123-41116 Status: PR Insp. Status: RI

Producing Well

Comment: [PR, stormwater inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Sediment Traps	Pass					see comments

Comment: Repairs were made to the berm BMP along portions of the northern and southern location, and along the western location. Berm BMP has been repaired and built up higher. Appears minor repairs were made to the sediment traps. Appears the holding capacity for both sediment traps may be insufficient. Wattles are being used as outlet protection which may not be appropriate for long-term outlet protection as wattles are a temporary BMP. The performed work on the sediment traps may be insufficient to prevent sediment laden stormwater runoff from leaving location. As it was noted in the previous inspection, sediment discharge was evident from the outlet areas on both sediment traps.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682401966.	binschusc	04/05/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401966	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116893