

Well Information

Well Name	Rein 11-32
API	05-123-12939
SHL	NESW 32 5N63W 6 PM
Latitude	40.354076
Longitude	-104.462482
Date of Plan	4/11/2017
Surface Casing Set Depth	326
TD	6645

Procedure

- 1 Contact landowner and state representative 48 hours prior to commencing work on this well
- 2 Build temporary pad and access road for completion rig and cement unit
- 3 Cut off dry hole marker
- 4 Verify pipe size and weld on wellhead flange and riser
- 5 MIRU completion rig
- 6 MU BHA
- 7 RIH to 376' and drill out existing cement plugs
- 8 Continue to circulate mud to ensure hole clean out
- 9 Trip in to existing hole to 580' or as deep as possible without turning a bit
- 10 POOH and LD BHA
- 11 TIH to 530'
- 12 RU Cementers
- 15 Pump 126 sx balanced plug to surface
- 16 POOH and LD tubing
- 17 RDMO completion rig
- 18 Dump 50' cement inside and outside surface casing
- 19 Cut off wellhead and riser to 4' below ground level
- 20 Weld on dry hole marker
- 21 Clean location and reclaim

Before Plugging:

8 5/8" 24# Surface Set @ 326

Cement Plug 10 sk at surface


40 sk Cement Plug at 326'

CIBP 6200' & 3 sk cement on top

7 7/8" Open Hole TD @ 6645

Top of 4 1/2 11.6# casing at 5560'

Top of cement at 5572'



After Plugging:

8 5/8" 24# Surface Set @ 326

Cement Plug 530' - Surface

CIBP 6200' & 3 sk cement on top

7 7/8" Open Hole TD @ 6645

Top of 4 1/2 11.6# casing at 5560'

Top of cement at 5572'

