

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/24/2017

Document Number:

674901626**FIELD INSPECTION FORM**

Loc ID 385890 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 87830Name of Operator: THOMPSON ENGINEERING & PRODUCTIONAddress: 7415 E MAINCity: FARMINGTON State: NM Zip: 87402**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Paul		paul@walsheng.net	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89116	WELL	PR	12/12/2011	GW	067-08220	BONDAD 33-9 34A	EI

General Comment:

On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Thompson Engineering and Production Co. Bondad 33-9 #34A. For the most recent field inspection report for this facility, please refer to document #674600371.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign near produced water tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	No label or placard observed on chemical injection container.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Fencing around perimeter of produced water tank secondary containment.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical injection system.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.106043,-107.794103
Comment:	Expanded metal cover.				

Corrective Action:		Date:		
Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity) 95 bbl.				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:		Capacity does not appear to be sufficient.		
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 605.a.(4).		Date: 05/24/2017
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	89116	Type:	WELL	API Number:	067-08220	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Location berm on S and E sides. Secondary containment for chemical injection system.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Thompson Engineering and Production Co. Bondad 33-9 #34A. For the most recent field inspection report for this facility, please refer to document #674600371. The secondary containment berm appears to have insufficient capacity for the open topped produced water tank.	hughesj	04/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901627	Chemical injection system with secondary containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130704
674901628	PW open topped AST with insufficient berm.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130705