

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2017

Submitted Date:

05/01/2017

Document Number:

680601494

FIELD INSPECTION FORM

Loc ID 326593 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, General		COGCCinspectionreportsSan Juan@wpxenergy.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258550	WELL	PR	10/09/2001	GW	067-08365	BONDAD 33-10 5A	RI

General Comment:

[This is a followup inspection for inspection number 680601149 conducted on December 9, 2016.](#)

Inspected Facilities

Facility ID: 258550 Type: WELL API Number: 067-08365 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosional features noted in the December 2016 inspection have been filled. However, recent grading of the roadside ditches, scouring of the well pad diversion, and scraping in the southeastern portion of the project area have exposed soils and damaged vegetation, appearing to be accelerating erosion within the project area. No effective stormwater controls have been installed. See attached photos.

Corrective Action: This is the second corrective action for stormwater erosion within the project area as corrective actions are not sufficiently addressed. Diversions and roadside ditches need stormwater controls to de-energize stormwater flows and catch sediment. Culvert on the access road needs further stabilization as soil placed on top will only erode back into the drainage. Revegetation is needed where vegetation has been damaged or removed or to stabilize exposed soils. Corrective action date for corrective actions documented in Decemner inspection will remain the same. Stormwater erosion needs to be controlled within the project area by May 15, 2017.

Date: 04/01/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401271002	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136095
680601495	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136094