

REENTRY PROCEDURE

WELL NAME: Jude 1 **DATE:** 5/12/2017
LOCATION:
 Qtr/Qtr: SWNW Section: 9 Township: 5N Range: 62W
COUNTY: WELD **STATE:** CO **API #:** 05-123-10501
ENGINEER: David Hughes **7 Day Notice Sent:** _____
 (Please notify Engineer of any major changes prior to work) **Do not start operations until:** _____
Notice Expires: _____
OBJECTIVE: Reenter and re-plug
WELL DATA: Surface Csg: 8 5/8" 24# @ 191' KB Elevation: 4717'
 Surface Cmt: 175 SX GL Elevation: 4707'
 Long St Csg: N/A MD: 7070'
 Long St Cmt: N/A PBTD: _____
 Long St Date: N/A
 Plug Info (1) Shoe Plug: 123'-191' 20 SX
 Plug Info (2) Surface Plug: Surface-61' 15 SX
 Plug Info (3) _____
 Plug Info (4) _____
 Tubing: _____ Rods: _____
 Pump: _____
 Misc.: Base Fox Hills 372', Deepest Water Well 45'
WELL STATUS: Well Abandoned 12/21/1981
COMMENTS: ***LIMITED DATA ON RECORD - PROCEED WITH CAUTION***

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake and take location photos
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5K BOP, test BOP.
- 8) NU and RIH with 6 1/8" cone bit, PU 2 7/8" drill collars, 2 7/8" 6.5# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing (TOC @ surface) tag second plug at 123', roll hole clean.
- 10) Pressure test surface casing to 200 psi. If pressure bleeds off, set RBP and test again. ****If test fails, contact office.****
- 11) After pressure test of surface casing, drill out second cement plug from 123' to 191'
- 12) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 13) Continue RIH, cleaning out with drilling mud or water to 6250' (Nio top @ 6278'). ****If unable to get to depth, contact office****
- 14) TOOH with cone bit, drill collars, and 2 7/8" tubing.
- 15) PU and RIH with mule shoe and 2 7/8" tubing to 6250'.
- 16) RU cement crew and pump 100 sxs of 15.8ppg Class G "neat" balanced plug to 6000'

Interval Start	Interval End	Length (ft)	Vol. Factor (ft^3/ Volume (ft^3)	Yield (ft^3/sk)	Cement (sxs)
6250	6000	250	0.4418	110	1.15

- 17) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC.

- 18) Pump 100 sxs of 15.8ppg Class G "neat" cement courtesy plug from 3000' to 2750'

Interval Start	Interval End	Length (ft)	Vol. Factor (ft^3/ Volume (ft^3)	Yield (ft^3/sk)	Cement (sxs)
3000	2750	250	0.4418	110	1.15

- 19) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC.