

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2017

Submitted Date:

09/27/2017

Document Number:

680602030

**FIELD INSPECTION FORM**

Loc ID 316833 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10453  
Name of Operator: PARADOX UPSTREAM LLC  
Address: 600 TRAVIS STREET SUITE 300  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Nowak, Scott		scottn@bogresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264710	WELL	SI	01/01/2017	GW	113-06109	FOSSIL FEDERAL 1-20	RI

**General Comment:**

*This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.*

**Inspected Facilities**

Facility ID: 264710 Type: WELL API Number: 113-06109 Status: SI Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by mixed grassland and sagebrush shrubland. Revegetation is progressing within the interim reclamation area. See attached photos.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater flows are diverted from the southern edge, and northward along the western edge of the project area, parallel to an existing channel. Rilling is occurring within the western fill slope of the well pad and should be monitored and BMPs applied if it worsens. See attached photos.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680602031	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262582</a>