

### **Summary of Re-entry and Re-plugging Operations**

1. Survey and locate plugged wellbore. Set a stake and record as-drilled GPS coordinates.
2. Excavate around wellbore to expose the top of the surface casing.
3. Cut existing cap off wellbore. Weld a crossover from 10-3/4" casing to 8-5/8" casing and necessary length of casing to reach ground level. Weld an 8-5/8" slip collar.
4. Install wellhead and BOP.
5. Drill out existing cement plugs with 6-1/2" bit. Pressure test surface casing to 250 psi before drilling out surface casing plug. Continue drilling or RIH to 6270'.
6. Spot cement plug from 6270'-6170' with class G cement (33 sks).
7. Pull up and spot plug from 6055'-5755' with class G cement (99 sks). Tag plug once set.
8. Spot plug from 515' to surface with class G cement (199 sks).
9. Cut off casing 5' below surface and weld on a cap to seal the well.
10. Cover up the well and remediate the disturbed area.