

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401355840
Date Received:
07/27/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Michael Gardner	970-623-4875	mgardner@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674300895
Inspection Date: 05/03/2017 FIR Submit Date: 05/04/2017 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 432702

Location Name: Beaver Creek Frac Pad Number: 11-7-793 County: _____
Qtrqr: NWN Sec: 7 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.459362 Longitude: -107.823200

FACILITY - API Number: 05-045- -00 Facility ID: 448367

Facility Name: BEAVER CREEK Number: 11-7-793
Qtrqr: NWN Sec: 7 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.459362 Longitude: -107.823200

CORRECTIVE ACTIONS:

1 ☒ CA# 74667

Corrective Action: Label new tanks. Remove any tanks which are no longer in use. Maintain erosion control BMPs on cut slope to prevent sedimentation and excess run on to pad. Date: 08/04/2017

Response: CA COMPLETED Date of Completion: 06/29/2017

Operator Comment: Tanks have been labeled. Regarding the soil slump area on the cut slope, TEP's Production Supervisor and a construction contractor reviewed cut slope area and have determined that any attempts to repair the area would do more harm than good at this point. There is good vegetation becoming established on the slope which is helping to stabilize the soil slump area. Any disturbance will only further destabilize the area, and could potentially cause a bigger issue. It is recommended that TEP continue to monitor the slump area through the

spring of 2018. We believe that the slump area will stabilize, but it will be reevaluated at that time to determine if further action is needed.

Existing BMPs are sufficient to prevent off-site sedimentation

COGCC Decision: Approved

COGCC Representative: All CAs from inspection completed. Close.

OPERATOR COMMENT AND SUBMITTAL

Comment: Tanks have been labeled. TEP will continue to monitor soil slump area to determine if further action is needed. Current BMPs are functioning as designed and are effectively controlling off-site sedimentation and erosion.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 7/27/2017 9:51:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401355840	FIR RESOLUTION FORM
401356118	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files