

FORM  
6Rev  
12/05

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

401479489

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Jenifer Hakkarinen

Name of Operator: PDC ENERGY INC

Phone: (303) 8605800

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: Jenifer.hakkarinen@pdce.com

**For "Intent" 24 hour notice required,**

Name: Peterson, Tom

Tel: (303) 815-9641

**COGCC contact:**

Email: tom.peterson@state.co.us

API Number 05-123-20659-00

Well Name: FICKEL

Well Number: 41-21

Location: QtrQtr: NENE Section: 21 Township: 4N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.304140

Longitude: -104.888110

GPS Data:

Date of Measurement: 07/15/2010

PDOP Reading: 1.6

GPS Instrument Operator's Name: Holly L. Tracy

Reason for Abandonment:

☐ Dry☒ Production Sub-economic☐ Mechanical Problems☐ Other

Casing to be pulled:

☒ Yes☐ No

Estimated Depth: 615

Fish in Hole:

☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☒ No

If yes, explain details below

Details:

### Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7275	7285			

Total: 1 zone(s)

### Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	401	280	401	0	VISU
1ST	7+7/8	4+1/2	10.5	7,441	200	7,441	6,440	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7225 with 2 sacks cmt on top. CIBP #2: Depth 6905 with 2 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 330 sks cmt from 665 ft. to 0 ft. Plug Type: STUB PLUG Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 4950 ft. with 195 sacks. Leave at least 100 ft. in casing 4565 CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

Fickel 41-21 (05-123-20659)/Plugging Procedure (Intent)  
Producing Formation (Perforations): Codell: 7275'-7285'  
TD: 7480' PBD: 7429'  
Surface Casing: 8 5/8" 24# @ 401' w/ 280 sxs  
Production Casing: 4 1/2" 10.5# @ 7441' w/ 200 sxs cmt (TOC @ 6440' - CBL).

Tubing: 2 3/8" tubing set @ 7266' (4/4/2002).

Proposed Procedure:

1. Run gyro survey.
  2. MIRU pulling unit. Pull 2 3/8" tubing.
  3. RU wireline company.
  4. TIH with CIBP. Set BP at 7225'. Top with 2 sxs 15.8#/gal CI G cement.
  5. TIH with CIBP. Set BP at 6905'. Top with 2 sxs 15.8#/gal CI G cement.
  6. Shoot lower squeeze holes at 4950'. Shoot upper squeeze holes at 4550'.
  7. Set CICR at 4565'. Sting in and pump 195 sxs 15.8#/gal CI G cement. Sting out and pump 10 sxs on top of CICR.
  8. TIH with casing cutter. Cut 4 1/2" casing at 615'. Pull cut casing.
  9. TIH with tubing to 665'. RU cementing company. Mix and pump 330 sxs 15.8#/gal CI G cement down tubing. Cement should circulate to surface.
  10. Cut surface casing 6' below ground level and weld on cap.
- If there is bradenhead pressure:
1. Run gyro survey.
  2. MIRU pulling unit. Pull 2 3/8" tubing.
  3. RU wireline company.
  4. TIH with CIBP. Set BP at 7225'. Top with 2 sxs 15.8#/gal CI G cement.
  5. TIH with CIBP. Set BP at 6905'. Top with 2 sxs 15.8#/gal CI G cement.
  6. Shoot lower squeeze holes at 4950'. Shoot upper squeeze holes at 4550'.
  7. Set CICR at 4565'. Sting in and pump 195 sxs 15.8#/gal CI G cement. Sting out and pump 10 sxs on top of CICR.
  8. TIH with casing cutter. Cut 4 1/2" casing at 1500'. Pull cut casing.
  9. TIH with tubing to 1550'. RU cementing company. Mix and pump 75 sxs 15.8#/gal CI G cement down tubing. Wait 8 hours or overnight. Check to see if there is any bradenhead pressure or fluid flow after stub plug is set. If there is, contact COGCC for further guidance. If there is not, move on to step 8.
  10. TIH with tubing to 615'. RU cementing company. Mix and pump 450 sxs 15.8#/gal CI G cement down tubing. Cement should circulate to surface.
  11. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Jenifer Hakkarinen

Title: Reg Tech

Date: \_\_\_\_\_

Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

Expiration Date: \_\_\_\_\_

**COA Type**

**Description**

--	--

**Attachment Check List**

**Att Doc Num**

**Name**

401479546	WELLBORE DIAGRAM
401479547	WELLBORE DIAGRAM

Total Attach: 2 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)