

FORM  
6Rev  
12/05

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number:  401492702			
Date Received:			

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175	Contact Name: Jenifer Hakkarinen
Name of Operator: PDC ENERGY INC	Phone: (303) 8605800
Address: 1775 SHERMAN STREET - STE 3000	Fax:
City: DENVER State: CO Zip: 80203	Email: Jenifer.Hakkarinen@pdce.com
<b>For "Intent" 24 hour notice required,</b> Name: Peterson, Tom Tel: (303) 815-9641 <b>COGCC contact:</b> Email: tom.peterson@state.co.us	

API Number 05-069-06336-00	Well Number: 23-25U
Well Name: RYAN	
Location: QtrQtr: NESW Section: 25 Township: 5N Range: 68W Meridian: 6	
County: LARIMER	Federal, Indian or State Lease Number:
Field Name: JOHNSON'S CORNER	Field Number: 42570

☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.368610	Longitude: -104.956940
GPS Data:	
Date of Measurement: 10/31/2007	PDOP Reading: 5.3
GPS Instrument Operator's Name: HOLLY L. TRACY	
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems	
<input type="checkbox"/> Other	
Casing to be pulled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Estimated Depth: 675
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below
Details:	

### Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7070	7078			
NIOBRARA	6754	6843			
Total: 2 zone(s)					

### Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	456	320	456	0	VISU
1ST	7+7/8	4+1/2	10.5	7,655	235	7,655	6,226	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7481 with 2 sacks cmt on top. CIPB #2: Depth 6704 with 2 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 345 sks cmt from 725 ft. to 0 ft. Plug Type: STUB PLUG Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

Ryan 23-25U (05-069-06336)/Plugging Procedure (Intent)  
Producing Formation (Perforations): Niobrara: 6754'-6843' Codell: 7070'-7078' J-Sand: 7531'-7545'  
TD: 7705' PBD: 7633'  
Surface Casing: 8 5/8" 24# @ 456' w/ 320 sxs  
Production Casing: 4 1/2" 10.5# @ 7655' w/ 235 sxs cmt (TOC @ 6226' - CBL).

Tubing: 2 3/8" tubing set @ 7516' (1/30/2017).

Proposed Procedure:

1. Run gyro survey.
  2. MIRU pulling unit. Pull 2 3/8" tubing.
  3. RU wireline company.
  4. TIH with CIBP. Set BP at 7481'. Top with 2 sxs 15.8#/gal CI G cement.
  5. TIH with CIBP. Set BP at 6704'. Top with 2 sxs 15.8#/gal CI G cement.
  6. TIH with casing cutter. Cut 4 1/2" casing at 675'. Pull cut casing.
  7. TIH with tubing to 725'. RU cementing company. Mix and pump 345 sxs 15.8#/gal CI G cement down tubing. Cement should circulate to surface.
  8. Cut surface casing 6' below ground level and weld on cap.
- If there is bradenhead pressure:
1. Run gyro survey.
  2. MIRU pulling unit. Pull 2 3/8" tubing.
  3. RU wireline company.
  4. TIH with CIBP. Set BP at 7481'. Top with 2 sxs 15.8#/gal CI G cement.
  5. TIH with CIBP. Set BP at 6704'. Top with 2 sxs 15.8#/gal CI G cement.
  6. TIH with casing cutter. Cut 4 1/2" casing at 1500'. Pull cut casing.
  7. TIH with tubing to 1550'. RU cementing company. Mix and pump 75 sxs 15.8#/gal CI G cement down tubing. Wait 8 hours or overnight. Check to see if there is any bradenhead pressure or fluid flow after stub plug is set. If there is, contact COGCC for further guidance. If there is not, move on to step 8.
  8. TIH with tubing to 675'. RU cementing company. Mix and pump 475 sxs 15.8#/gal CI G cement down tubing. Cement should circulate to surface.
  9. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jenifer Hakkarinen  
Title: REg TEch Date: \_\_\_\_\_ Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Expiration Date: \_\_\_\_\_

COA Type	Description
----------	-------------

--	--

### Attachment Check List

Att Doc Num	Name
-------------	------

401492709	WELLBORE DIAGRAM
401492710	WELLBORE DIAGRAM

Total Attach: 2 Files

### General Comments

User Group	Comment	Comment Date
------------	---------	--------------

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)