

Document Number:
401518042

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175 Contact Name: Kelsi Welch
 Name of Operator: PDC ENERGY INC Phone: (303) 831-3974
 Address: 1775 SHERMAN STREET - STE 3000 Fax: _____
 City: DENVER State: CO Zip: 80203 Email: kelsi.welch@pdce.com

For "Intent" 24 hour notice required, Name: Montoya, John Tel: (970) 397-4124
 COGCC contact: Email: john.montoya@state.co.us

API Number 05-123-20391-00 Well Number: 13-3D
 Well Name: MILLAGE
 Location: QtrQtr: NWSW Section: 3 Township: 5N Range: 64W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.427640 Longitude: -104.543060
 GPS Data:
 Date of Measurement: 05/17/2008 PDOP Reading: 2.2 GPS Instrument Operator's Name: Holly L. Tracy
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	6851	6859	12/15/2017	B PLUG CEMENT TOP	6801
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	366	260	366	0	VISU
1ST	7+7/8	4+1/2	10.5	7,003	190	7,003	5,720	CBL
S.C. 1.1				7,003	200	5,800	3,390	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6801 with 2 sacks cmt on top. CIBP #2: Depth 6577 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 285 sks cmt from 825 ft. to 0 ft. Plug Type: STUB PLUG Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 10 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 720 ft. of 4+1/2 inch casing Plugging Date: 12/18/2017
 *Wireline Contractor: Casedhole Solutions *Cementing Contractor: C&J
 Type of Cement and Additives Used: 15.8#/gal CI G cement with 2% CaCl
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Millage 13-3D (05-123-20391)/Plugging Procedure (Subsequent)
 Producing Formation: Codell 6851'-6859'
 TD: 7046' PBD: 6990'
 Surface Casing: 8 5/8" 24# @ 366' w/ 260 sxs.
 Production Casing: 4 1/2" 10.5 & 11.6# @ 7003' w/ 390 sks cmt. (TOC at 3332' CBL.)

Tubing: 2 3/8" tubing set at 6793'. (11/5/2002)

Proposed Procedure:

1. MIRU RU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company. Run Gyro survey from 6850' to surface.
3. TIH with CIBP. Set BP at 6801'. Top with 2 sxs 15.8#/gal CI G cement.
4. TIH with CIBP. Set BP at 6577'. Top with 2 sxs 15.8#/gal CI G cement.
5. TIH with casing cutter. Cut 4 1/2" casing at 720'. Pull cut casing.
6. TIH with tubing to 825'. RU cementing company. Mix and pump 285 sxs 15.8#/gal CI G cement with 2% CaCl down tubing to surface.
7. Top off surface plug with 10 sxs 15.8#/gal CI G cement.
8. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kelsi Welch
 Title: Production Tech Date: _____ Email: kelsi.welch@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

<u>COA Type</u>	<u>Description</u>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401518047	WIRELINER JOB SUMMARY
401518049	CEMENT JOB SUMMARY
401518051	WELLBORE DIAGRAM
401518052	CEMENT BOND LOG

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)