



SRC ENERGY

**Operator:** Prima Oil & Gas Company  
**Well Name:** Walker 11-18  
**Legal:** NWNW, Section 18, Township 6N, Range 66W  
**Location:** Weld County, CO  
**API:** 05-123-11115  
**Surface:** 8.625" 24# @ 496'      **Hole Size:** 12.25"      **TOC:** Surface  
**Production:** 4.5" 11.6# @ 7,330'      **Hole Size:** 7.875"      **TOC:** 6,408' & 4,460' (CBL)  
**Perforations:** 4,752' – 4,760' (Shannon), 7,234' – 7,245' (Codell)  
**TD:** 7,330'

P&A Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Dig out to find wellhead and check pressure
3. Cut cap off, extend surface pipe to achieve ground level
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe to be ran in well
5. Mill through the 2 cement plugs in the surface casing
  - a. Surface plug – 15 sx (≈55' plug)
  - b. SC Shoe plug – 45 sx (≈143' plug)
6. Wash run to depth that well allows
7. TOOH, remove BHA for milling
8. TIH to 4,315' based off of pipe tally and pump a 500' stub plug (3,815'-4,315')
  - a. 184 sx of 15.8# class G neat 1.15 cu/ft yield cement
  - b. Wait 4 hours and tag plug
9. TIH to 2,500' based off of pipe tally and pump a 500' open hole plug (2,000'-2,500')
  - a. 184 sx of 15.8# class G neat 1.15 cu/ft yield cement
  - b. Wait 4 hours and tag plug
10. TIH to 820' based off of pipe tally and pump a 820' surface plug (0'-820')
  - a. 290 sx of 15.8# class G neat 1.15 cu/ft yield cement
  - b. Wait 4 hours and tag plug
11. RDMO WO unit
12. Remove extension of surface pipe. Top off if necessary.
13. Weld on cap with ID plate, inscribed with well location, and identity
14. Backfill, clean location
15. Re-Entry to Re-plug complete