

## Recompletion Procedure Quiver Unit #10

1. TOH with tubing, rods & pump.
2. Set CIBP at ~5351' to abandon the Spergen Formation.
3. Perforate squeeze holes at 4990'.
4. Set cement retainer at ~4980'.
5. TIH w/stinger and tubing. Sting into cement retainer.
6. Acidize squeeze perfs with 500 gals. 15% MCA & establish injection rate.
7. Pump 100 sacks cement with fluid loss additive in first 75 sacks.
8. Sting out of retainer and circulation clean.
9. Run CBL to determine top of cement and verify we have cement up to at least 4800'.
10. Drill out cement retainer & test casing to 500 psig.
11. Perforated the St. Louis formation at 5028'-5032'.
12. TIH with packer and tubing. Set packer and swab test.
13. Acidize St. Louis formation with 500 gals. 15% MCA and 1000 gals. MOD-202 acid.
14. Swab back load & swab test.
15. TOH with tubing and packer.
16. Run tubing, pump and rods.
17. Put well on production.