

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2018

Submitted Date:

02/26/2018

Document Number:

690100388

FIELD INSPECTION FORM

Loc ID 329323 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	
,		cogccinspections@srcenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249354	WELL	SI	09/01/2017	OW	123-17156	LUCERO 34-10	EG

General Comment:

Engineering Integrity Inspection performed on February 14th, 2018 in response to initial form 19 spill report Doc #401541390 received by COGCC on 02/12/2018 that outlines: On Monday 2/5/18, the line was pressure tested by SRC's Facilities group, where they found the line to have a leak somewhere between the wellhead and tank battery to the southwest. They then isolated segments of the line to determine where exactly the leak in the line was. A hammer union was found to be at this point in the flowline. Details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities			
Facility ID: <u>249354</u>	Type: <u>WELL</u>	API Number: <u>123-17156</u>	Status: <u>SI</u> Insp. Status: <u>EG</u>
Flowline			
#1	Type: Well Site	1 of Lines	
Flowline Description			
Flowline Type: <u>Well Site</u>	Size: <u>2"</u>	Material: <u>Carbon Steel</u>	
Variance: <u>No</u>	Age: <u>20+ Yrs</u>	Contents: <u>Multiphase</u>	
Integrity Summary			
Failures: <u>External Corrosion</u>	Spills: <u>Yes</u>	Repairs Made: <u>Yes</u>	
Coatings: <u>Yes External</u>	H2S: <u>No</u>	Cathodic Protection: <u>No</u>	
Pressure Testing			
Witnessed:	Test Result:	Charted:	
COGCC Rules(check all that apply)			
<input type="checkbox"/> 1101. Installation and Reclamation <input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:	There were (2) flowline failure points identified on the offsite flowline routed between the wellhead and horizontal separator. The flowline runs SW approximately 600' from the wellhead to facility. Both failures were attributed to buried hammer unions (installed by a previous operator). External corrosion occurred at the threaded connections found uncoated/ unwrapped. The hammer unions were removed and valves installed on the ends of the flowline. Approximately 40' of flowline was removed at the facility and near the separator inlet, scheduled to be replaced. There were no SRC Energy employees or contractors on site at the time of this field inspection.		
Corrective Action:	As outlined by SRC Energy on supplemental form 19 doc #401549485 received on 02/20/2018: The flowline leak was discovered when pressure testing the flowline from the separator to the wellhead, and then pressure testing the line in 3 different segments. After uncovering the buried line, it was found that this leak was caused from burying a 2" hammer union and screw pipe that was not coated. The schedule 80 screw pipe had corrosion and no fusion bond coating on the flowline. SRC Energy will install a new schedule 40 fusion bond welded flowline and do the necessary pressure testing before putting the well and flowline back in service.		
			Date:

COGCC Comments		
Comment	User	Date
Note: There are (2) form 19 spill reports filed by SRC Energy, one for each release point identified (Doc #401541390 on 02/12/2018 for 40.441788, -104.762612 and Doc #401546313 on 02/15/2018 for 40.442047, -104.762158)	maclarej	02/26/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401555051	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386646
690100407	Wellhead, signage and flowline work in progress	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386642
690100408	Flowline exposed near battery, spill ID 454050	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386643
690100409	Flowline betw wellhead/ separator spill ID 454029	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386644

690100410	Section of flowline removed near separator tie in	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386645
-----------	---	---