

Anderson 5
05-001-08160
P&A Procedure



NWNW Sec 10 T2S R61W

KB (Kelly Bushing): 5,031'

Adams, CO

Logger TD: 6,840' KB

GL (Ground Level): 5,018'

Surface Casing: 8 5/8" 24#/ft set @ 217' KB, cement to surf w/ 200 sx

Production Casing: 4 1/2", 11.6 #/ft, set @ 6,840' KB, cemented w/ 200 sx

Perfs: D Sand: 6,740'-6,758'

TOC - (Top of Cement)

MIRU - (Move in Rig Up)

CIBP - (Cast Iron Bridge Plug)

CICR- (Cast Iron Cement Retainer)

TAC - (Tubing Anchor Catcher)

- 1) Perform Bradenhead test. Sample any fluid or gas present on bradenhead and provide to the state.
- 2) MIRU workover rig, pump and tank
- 3) Kill well as necessary with treated water
- 4) Unhang Poolish rod. POOH LD rods & rod pump.
- 5) NDWH, NUBOPE
- 6) Un-land 2 3/8" production tubing, POOH w/ TBG
- 7) RUWL, Run gyro survey
- 8) Run CBL
- 9) RIH & perforate 3 jsf, @ 5,000-5,002. RDWL.
- 10) PU CICR & RIH on 2 3/8" tbg. Set CICR @ 50' above squeeze perforations ~ 4,950'),
- 11) RU Cementers and squeeze perforations with 50 sx cement. Displace cement out retainer, sting out of CICR & dump 2 sx cmt on top of CICR.
- 12) POOH LD TBG.
- 13) Un-land 4 1/2" casing
- 14) Attempt to cut 4 1/2" casing at 1,100' or at the shallowest freepoint, (minimum 450') and TOOH
- 15) RIH with 2 3/8" tubing to 200' below casing stub
- 16) RU cementers
- 17) Pump a 300 sx cement plug from EOT to surface
- 18) Tag up on cement or confirm to surface
- 19) RDMO location with workover rig
- 20) Dig up and cut casing below surface (6'), weld on dry hole marker
- 21) Remove all surface facilities related to the Anderson #5.
- 22) Restore Pad as per state requirements.