



Photo 1. View of the project area from the western edge facing toward the center of the southern working area. Staked well is in place.



Photo 2. View of the southwestern portion of the project area from the western edge facing southward. Revegetation is progressing with shrubs and grasses such as rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron cristatum*), and smooth brome (*Bromus inermis*).



Photo 3. View of the northwestern corner of the northern portion of the project area facing southward.



Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 5. View of newly installed culvert outlet along the access road. It does not appear that stormwater flows exiting the culvert will be properly de-energized and will likely erode down the slope. Erosion and sediment controls should be installed to de-energize flows exiting the culvert and filter sediment. Loose soils need to be stabilized.



Photo 6. View of another newly installed culvert where loose soils are not properly stabilized and stormwater flows are diverted downslope without proper erosion and sediment controls.