

<b>Operator:</b>	SRC Energy			
<b>Well Name:</b>	EHRlich #14-31			
<b>Legal:</b>	NESW 14 4N67W			
<b>Location:</b>	Weld County, CO			
<b>API:</b>	05-123-19464			
<b>Surface:</b>	8.625" 24# @	408'	<b>Hole Size:</b> 12.25"	<b>TOC:</b> Surface
<b>Production:</b>	4.5" 11.6# @	7307'	<b>Hole Size:</b> 7.875"	TOC: 0' (CBL)
<b>Perforations:</b>	7203-7213 CODELL			
<b>TD:</b>	7340			

#### P&A Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Blow down well if necessary, circulate hole with treated water
3. Dig out around wellhead and perform bradenhead test
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe
5. TIH w/ 4-1/2" 11.6# CIBP on tubing, set at 6859'
6. Pressure test casing to 500 psi for 15 minutes
7. Run CBL from CIBP to surface. Report results to office. Procedure may change based on results.
8. Set 35 sx on top of existing CIBP (cover 375' above Niobrara top)
9. RU Electric Line. TIH w/ 4-1/2" 11.6# CIBP, set at 2400'
  - a. Dump bail 2 sx of cement on top of CIBP
10. TIH with tubing to 1000' and pump stub plug from 1000 - 0'
  - a. pump 76 sks of 15.8# class G neat 1.15 cu./ft. yield cement
  - b. trip out of surface casing
  - c. Wait 4 hours and tag plug
11. RDMO WO unit
12. Dig up wellhead and cut off 10' below restored ground level, top off if necessary
13. Weld on cap with ID plate, inscribed with well location, and identity
14. Backfill, clean location
15. P&A complete