

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2018

Submitted Date:

09/25/2018

Document Number:

690900030**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: FISCHER, ALEX On-Site Inspection ☐
 2A Doc Num: _____
Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Haub, Mike	(970) 697-8385	MHaub@chevron.com	All Inspections
Arauzo, Steven		steven.arauza@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
149002	CENTRALIZED EP WASTE MGMT FAC	AC	08/23/2000		-	WILSON CREEK LANDFARM	EI

General Comment:

On September 20, 2018 COGCC Environmental Staff (Alex Fischer and Steven Arauzo) conducted an environmental field inspection of Chevron USA Inc. (Chevron) Wilson Creek Land Treatment Facility ID: 149002. Chevron personnel present included Mike Haub, and Adriane Gifford. Chevron's consultant (Stantec) Brent Lucyk was also present. Weather was sunny and temperature app 80 degree F. The following is a summary:

Land Treatment Facility 149002:

The following was observed at the CE&P Facility:

- Soil sampling of the land treatment area was being performed by Stantec.
- The north westerly area of the land treatment cell appeared to be recently tilled.
- An approximate 6 feet in height and approximate 30 feet in diameter soil stockpile was located in the north westerly land treatment cell.
- In some places berms were worn down.
- The lined treatment cell (north easterly) appeared to be recently tilled.
- The fence in the northeast corner had gaps where the wire was cut or broken.
- Monitoring Well 46 has been removed and will be replaced with MW 46R.
- Some trash and debris (liner and metal pieces) were observed in the treatment cells.

Inspected Facilities									
Facility ID:	149002	Type:	CENTRALIZE	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Land Treatment	Adequate		
Comment	<ul style="list-style-type: none"> • The north westerly area of the land treatment cell appeared to be recently tilled. • The lined treatment cell (north easterly) appeared to be recently tilled. 			
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
<p>Land Treatment Facility 149002:</p> <p>The following was observed at the CE&P Facility:</p> <ul style="list-style-type: none"> • Soil sampling of the land treatment area was being performed by Stantec. • The north westerly area of the land treatment cell appeared to be recently tilled. • An approximate 6 feet in height and approximate 30 feet in diameter soil stockpile was located in the north westerly land treatment cell. • In some places berms were worn down. • The lined treatment cell (north easterly) appeared to be recently tilled. • The fence in the northeast corner had gaps where the wire was cut or broken. • Monitoring Well 46 has been removed and will be replaced with MW 46R. • Some trash and debris (liner and metal pieces) were observed in the treatment cells. <p>Corrective Actions (CAs):</p> <p>Remove trash and debris (liner and metal pieces) during tilling operations and properly dispose.</p> <p>Maintain berm around the treatment cells and tracking control upon entrance into and out of the treatment area(s).</p> <p>Maintain fence around the perimeter of the land treatment cells to prevent livestock from accessing the Facility.</p> <p>Provide documentation that the monitoring well MW 46 was properly abandoned in accordance to the Division of Water Resources guidance.</p>	fischera	09/24/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900030	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590633
690900031	INSP Photo Wilson Creek CE&P 149002 20180920	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590631