

Document Number:  
 401798347  
 Date Received:

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10633 Contact Name: Toby Sachen  
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 410-8536  
 Address: 1801 CALIFORNIA STREET #2500 Fax: \_\_\_\_\_  
 City: DENVER State: CO Zip: 80202 Email: toby.sachen.contractor@crestonepr.com

**For "Intent" 24 hour notice required,** Name: Beardslee, Tom Tel: (970) 420-3935  
**COGCC contact:** Email: tom.beardslee@state.co.us

API Number 05-123-29898-00  
 Well Name: HALEY Well Number: 31-22  
 Location: QtrQtr: SENE Section: 22 Township: 2N Range: 68W Meridian: 6  
 County: WELD Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon  Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.127140 Longitude: -104.984223  
 GPS Data:  
 Date of Measurement: 02/17/2010 PDOP Reading: 2.0 GPS Instrument Operator's Name: ROB THOMAS  
 Reason for Abandonment:  Dry  Production Sub-economic  Mechanical Problems  
 Other \_\_\_\_\_  
 Casing to be pulled:  Yes  No Estimated Depth: 2000  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7646	7666			
J SAND	8080	8094			
NIOBRARA	7426	7446			

Total: 3 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	772	410	772	0	CALC
1ST	7+7/8	4+1/2	11.6	8,239	370	8,239	6,530	CBL
S.C. 1.1				5,234	160	5,234	3,820	CBL

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 8010 with 2 sacks cmt on top. CIBP #2: Depth 7310 with 2 sacks cmt on top.  
 CIBP #3: Depth 80 with 0 sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 5365 ft. to 5100 ft. Plug Type: CASING Plug Tagged:   
 Set 30 sks cmt from 4645 ft. to 4250 ft. Plug Type: CASING Plug Tagged:   
 Set 75 sks cmt from 2000 ft. to 1804 ft. Plug Type: OPEN HOLE Plug Tagged:   
 Set 20 sks cmt from 80 ft. to 0 ft. Plug Type: CASING Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 (Cast Iron Cement Retainer Depth)

Set 75 sacks half in. half out surface casing from 825 ft. to 624 ft. Plug Tagged:   
 Set \_\_\_\_\_ sacks at surface  
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
 Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
 \*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
 Type of Cement and Additives Used: \_\_\_\_\_  
 Flowline/Pipeline has been abandoned per Rule 1105  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

1. Perform Form 17 Bradenhead Test and sample for gas, water, and oil per COGCC Regulation. (not required if Bradenhead Test has been completed within 60 days of plugging operations.)
2. Contact surveyor to acquire as-built surface location.
3. Submit electronic Form 42 to COGCC 48 hours prior to MIRU.
4. Submit form for Ground Disturbance Permit. Get One Call.
5. Notify Automation and Production Department. Production to check pressures, retrieve plunger equipment and blow down well.
6. Hold a pre-job safety meeting. Discuss all aspects of the procedure with any involved personnel. Identify and address any safety concerns before the job begins.
7. MIRU workover unit. Blow down well.
8. ND wellhead. NU BOPE.
9. Un-land tubing and TOO H w/tubing.
10. MIRU wireline.
11. RIH w/ CIBP on wireline. Set CIBP at ~8,010' (within 50'-100' of the top of the J-Sand at 8,071', between collars).
12. RIH w/ wireline and dump bail 2 sx cement on top of CIBP. POOH.
13. RIH w/ CIBP on wireline. Set CIBP at ~7,310 (within 50'-100' of the top of the Niobrara at 7,365', between collars).
14. RIH w/ wireline and dump bail 2 sx cement on top of CIBP. POOH. Pressure test plug to 500 psi. If pressure test fails, contact engineering for next steps.
15. TIH w/ tubing to 5,365.
16. Pump 20 sx Class G balanced plug from 5,365 to 5,100' to cover stage tool. TOO H w/ tubing to 4645'.
17. Pump 30 sx Class G balanced plug from 4,645 to 4,250' (Sussex plug). TOO H w/ tubing.
18. ND 7 1/16" BOP and wellhead. NU 11" BOP on surface casing. RU casing tongs and pipe wrangler.
19. RIH with casing jet cutter on wireline. Cut 4 1/2" casing at 2,000. POOH with wireline. Pull casing with spear to first joint, remove casing slips. Establish circulation.
20. Pump and spot 75 sx Class G balance stub plug from 2,000' to 1,804'. Trip out of hole to 825'. Roll hole. Ensure there is no sign of hydrocarbons. If evidence is found, contact engineering. If circulation was not maintained, then the plug must be tagged after WOC.
21. Pump 75 sx Class G or Type III cement (mixed with sufficient accelerant to achieve a 4-hour set time) to spot a balanced plug across surface casing shoe. TOC will be approximately 624'. TOO H laying down all casing. Wait on cement long enough to ensure cement is set sufficiently to obtain a good tag and pressure test.
22. TIH w/ tubing and tag cement top. Per COGCC guidelines, cement top must be at 722' or higher. Report top to engineering. Pressure test plug to 250 psi. TOO H.
23. PU 8-5/8" CIBP. TIH and set @ 80'. Blow hole dry with rig compressor. TOO H. LD all tubing.
24. ND BOP. Install casing cap w/ relief valve.
25. Disconnect flowline from separator and connect to junk tank placed at the battery.
26. Flush flowline with treated fresh water then blow dry with rig compressor. Prepare flowline for removal by construction department.
27. RDMO pulling unit. Clean up location. Label all equipment to be sent to the yard with the well name.
28. MIRU top off truck, water truck, air compressor
29. RIH with plastic tubing at CIBP at 80'.
30. Reverse circulate with 20 sx of cement from 80' to surface. Top off well and annular spaces as needed.
31. RDMO top off equipment.
32. Per ground disturbance procedure/policy, excavate around wellhead. Notify Environmental Department for surface review and inspection while digging.
33. Contact EHS to scan WH with FLIR to confirm well is plugged with no gas at surface. Save FLIR photo in well file.
34. Cut off casing 4 ft below ground level.
35. Weld on metal plate and dry hole marker.
36. Remove flowlines and backfill holes.
37. Notify Integrity Department to properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment is complete.
38. Restore surface location.
39. Ensure all rig tickets, pressure charts, cement and wireline tickets are saved to the electronic well files on the shared drive for subsequent reporting.
40. Submit Form 6 Subsequent Report of Abandon

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Toby Sachen  
 Title: Contractor Date: \_\_\_\_\_ Email: toby.sachen.contractor@crestonepr.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: \_\_\_\_\_

<b>COA Type</b>	<b>Description</b>

## Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401798349	PROPOSED PLUGGING PROCEDURE
401798350	WELLBORE DIAGRAM

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)