

Inspection Photos

Operator: Enervest Operating, LLC

API: 05-067-06026

Date: 10/05/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is largely comprised of shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*) and big sagebrush (*Artemisia tridentata*), and weedy vegetation such as field bindweed (*Convolvulus arvensis*).



Photo 3. View of area in the southwestern project area where stormwater flows from the southwestern corner of the project area are diverted down slope resulting in soil erosion and sediment transport off of the project area.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of the northeastern project area where soils are not stabilized and berms/stormwater controls are not functioning properly.



Photo 6. View of erosional channel in the northwestern project, facing upslope, area where adjacent soils are not stabilized and stormwater flows erode the slope toward the western drainage.



Photo 7. Downstream view from Photo 7, facing downslope, where erosional channeling and rilling is occurring in the northwestern project area.