

Scheetz P5

API # 05-121-08983

Ground Level = 4,822' (KB = 8')

Casing = 5-1/2"

PBTD: 4315'

Perfs = 4,284'-4,295',



Scheetz P5 P&A Procedure**Day 1**

- 1) MI Codell Well Service and hold safety meeting
- 2) POOH with Tbg to derrick for what is needed to plug, lay down rest to be hauled.
- 3) RU Wireline, Set CIBP @ 4,230'. Dump 2 sks of Cement. CIBP 54' from perfs
- 4) RIH @ Perforate @ 3260' & 180'
- 5) Trip in Hole with Plugging Stands and Squeeze 40 sks to cover Niobrara

Day 2

- 6) POOH with Plugging stands, RIH and set CIBP @ 185'
- 7) Squeeze 50 sks @ 180'
- 8) Set 15 sxs of cement @ surface
- 9) RD Cementers, RDMO Codell Well Service
- 10) MIRU Welder Cut Casing 5' below surface and weld plate.
- 11) Cleanup Location prepare for Reclamation of Surface Facility