

FORM
6Rev
05/18

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400941607

Date Received:

11/23/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Jenifer Hakkarinen

Name of Operator: PDC ENERGY INC

Phone: (303) 8605800

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: Jenifer.Hakkarinen@pdce.com

For "Intent" 24 hour notice required,

Name: _____ Tel: _____

COGCC contact:

Email: _____

API Number 05-013-06091-00

Well Name: HOUSE

Well Number: 1-36

Location: QtrQtr: SESE Section: 36 Township: 2N Range: 70W Meridian: 6

County: BOULDER

Federal, Indian or State Lease Number: 10529

Field Name: WATTENBERG

Field Number: 90750

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.089145

Longitude: -105.171357

GPS Data:

Date of Measurement: 07/29/2010

PDOP Reading: 2.6

GPS Instrument Operator's Name: Shantell Kling

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other _____Casing to be pulled: ☐ Yes☐ No

Estimated Depth: _____

Fish in Hole: ☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7382	7414	09/23/2015	B PLUG CEMENT TOP	7335

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	523	350	523	0	VISU
1ST	7+7/8	5+1/2	15.5	7,613	250	7,613	6,480	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7335 with 25 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 12 sks cmt from 3518 ft. to 3388 ft. Plug Type: CASING Plug Tagged: ☒
Set 80 sks cmt from 2325 ft. to 1630 ft. Plug Type: CASING Plug Tagged: ☒
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 4500 ft. with 448 sacks. Leave at least 100 ft. in casing 3518 CICR Depth

Perforate and squeeze at 608 ft. with 120 sacks. Leave at least 100 ft. in casing 524 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☒ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: 10/05/2015

*Wireline Contractor: Magna/Nabors *Cementing Contractor: Magna

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

House 1-36
Post Plugging Procedure

Codell

Existing Perforations:

Codell: 7382'-7414'

PBTD: 7510'

8 5/8" 24# @ 523' w/ 350 sks cmt

5 1/2" 15.5# & 17# @ 7295' w/ 250 sks cmt (TOC @ 6000')

Procedure:

1. MIRU wireline
2. RIH set CIBP @ 7335'
3. RIH w/dump bailer and dump 25 sx cement on top of CIBP @ 7335'
4. RIH w/ perf guns shoot holes at 4500' and 3500'
5. RIH w/ CICR set @ 3518'
6. Sting into CICR pump 460 sxs, 448 sxs through CICR amd 12 sxs on top of CICR. Tag TOC @ 3388'
7. TIH w/ tubing to 2325' pump 80 sxs, tag TOC at 1630'
8. RIH w/ perf gun shoot holes at 608' and from 485'-493'
9. RIH w/ CICR set at 524'. Pump 120 sxs of cement, tag TOC at 5.5'
10. Cut casing and weld on cap

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Jenifer Hakkarinen

Title: Regulatory Tech

Date: 11/23/2015

Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Bouzek, Jared

Date: 1/10/2019

CONDITIONS OF APPROVAL, IF ANY:**COA Type****Description****Attachment Check List****Att Doc Num****Name**

2302969	GYRO SURVEY
400941607	FORM 6 SUBSEQUENT SUBMITTED
400941613	WELLBORE DIAGRAM
400941615	CEMENT BOND LOG
400941623	CEMENT JOB SUMMARY

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

Engineer	Received gyro. Still missing 42 flowline.	09/19/2018
Engineer	Missing gyro run during PA. Missing Fom 42 flowline.	09/13/2018

Total: 2 comment(s)