

<b>Operator:</b>	SRC Energy				
<b>Well Name:</b>	STUGART #22-20				
<b>Legal:</b>	SENW 20 5N 66W				
<b>Location:</b>	Weld County, CO				
<b>API:</b>	05-123-28089				
<b>Surface:</b>	8.625" 24# @	927'	<b>Hole Size: 12.25"</b>	<b>TOC: Surface</b>	
<b>Production:</b>	4.5" 11.6# @	7720'	<b>Hole Size: 7.875"</b>	<b>TOC: 1750' (CBL)</b>	
<b>Perforations:</b>	7543-7563 CODELL		7230-7450 NIOBRARA		
<b>TD:</b>	7736				

P&R Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Blow down well if necessary, circulate hole with treated water
3. Dig out around wellhead and perform bradenhead test
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe
5. TIH w/ 4-1/2" 11.6# CIBP on tubing, set at 7155'
6. Run CBL from 7155' to surface
7. Pressure test casing to 500 psi for 15 minutes
8. Set 10 sx on top of existing CIBP
9. TIH w/ 4-1/2" 11.6# CIBP, set at 2400'
  - a. Spot 9 sx of cmt on top of CIBP (120' casing plug)
10. Cut 4.5" casing @ 1027'
11. TIH with tubing to 1077' and pump stub plug from 0 - 1077'
  - a. pump 335 sks of 15.8# class G neat 1.15 cu./ft. yield cement
  - b. trip out of surface casing
  - c. Wait 4 hours and tag plug
12. RDMO WO unit
13. Dig up wellhead and cut off 10' below restored ground level, top off if necessary
14. Weld on cap with ID plate, inscribed with well location, and identity
15. Backfill, clean location
16. P&A complete