

Inspection Photos

API: 05-071-09381

Operator: XTO ENERGY INC

Inspection Date: 2/27/2019

Inspection Photos



Photo 1. Facing north at the beginning of the access road. Sediment has filled in the cattle guard and is being deposited in the roadway.

Inspection Photos



Photo 2. Erosion channels have developed on the access road

Inspection Photos



Photo 3. The cut slope areas along the access road are not stabilized and are susceptible to erosion.

Inspection Photos



Photo 4. Facing northwest along the access road. Stormwater is creating erosion channels on the road.

Inspection Photos



Photo 5. Facing northwest along the access road. Stormwater is creating erosion along the side of the road. No BMP's are installed to prevent erosion.

Inspection Photos



Photo 6. The access road appears to continue past the location.

Inspection Photos



Photo 7. Facing west toward the location. An erosion channel has developed at the pad.

Inspection Photos



Photo 8. The erosion channel at the east side of the location is causing erosion down the side of the access road. (shown in photo 5)

Inspection Photos



Photo 9. East side of the location facing toward the cut slope. The cut slope is not stabilized with vegetation. There are signs of soil sloughing and erosion.

Inspection Photos



Photo 10. Southwest side of the location facing north toward the cut slope.

Inspection Photos



Photo 11. Facing east along the fill slope. Vegetation has not established along the fill slope which is susceptible to erosion.

Inspection Photos



Photo 12. Southeast corner of the location facing northwest toward the cut slope. Vegetation has not established on the pad surface.

Inspection Photos



Photo 13. East side of the location facing north.