

Inspection Photos
Operator: Javernick Oil
Location/API #: 043-05088
Date: 2/28/2019



Photo 1. View of the western project area from the western edge facing southward. Wellhead is adjacent to an erosion channel. This area needs immediate stabilization to prevent any further erosion.



Photo 2. View of the well had from the southwestern edge facing northeastward. Active erosion is visible. Dark soils may indicate oil-stained soils. Location is not stable.



Photo 3. View of hydrocarbon material pooling around wellhead.



Photo 4. View of debris on the well pad.



Photo 5. View of barbed wire debris at the gated entrance to the well pad.



Photo 6. View of the project area from the northern edge facing southward.



Photo 7. View of the eastern project area from the southeastern edge facing northward.



Photo 8. View of stormwater diversion for run-on control along the eastern edge of the project area. Does not appear sufficient to divert stormwater flows from significant runoff events.



Photo 9. View of erosional headcut, approximately 3 feet wide and deep, along the eastern edge of the access road. Stormwater controls are needed to stabilize erosion within the roadside ditches.