

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2019

Submitted Date:

03/18/2019

Document Number:

694500058

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10551
Name of Operator: ANDEAVOR FIELD SERVICES LLC
Address: 1801 CALIFORNIA ST #1200
City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Schneider, Lindsay		Lindsay.Schneider@tsocorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463345	SPILL OR RELEASE	AC	03/15/2019		-	Duncan B-6 Lateral 276	EI

General Comment:

On 3/14/2019, COGCC Environmental staff, Kris Neidel inspected Spill Number 463345 on the Duncan B-6 Lateral 276. The weather was 40 degrees Fahrenheit, and clear following precipitation events the previous two days. The ground was saturated with stormwater and muddy. Two Andeavor Field staff were on location at the time of inspection (Alex and ??). Alex walked the spill with Kris. The pipe had failed at a spot where it crossed Vermillion Creek. The flow had eroded the soil below the spill point directly into the creek. Spilled fluid push upstream approximately 10 feet and downstream 60 feet. It was reported that snow was in the creek bed at the time the spill occurred. At the time of inspection, impacted portions of the creek were muddy and free of snow, where the non-impacted creek bed had approximately 2 inches of snow. The impacted areas had some dark stained soil that smelled of condensate. The areas that appeared to be remaining impact has a reflective shiny appearance. The non-impacted area of the creek had what appeared to be native coal fines and small pieces of coal, this native coal was observed across the spill area. The operator shall assess the extent of impact, remediate the impacted areas, and collect confirmation soil samples to verify remedial efforts. Documentation shall be provided on an eForm-27 and Supplemental eForm 27s on a monthly basis until remediation has been completed.

Inspected Facilities

Facility ID: 463345 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500059	potos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765697