

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2019

Submitted Date:

03/26/2019

Document Number:

688000284**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 YOUNG, ROB 2A Doc Num: _____

Operator Information:OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
109572	PIT	AC			-	DECKER "B"	EI
459085	SPILL OR RELEASE	AC			-	Pit Berm	EI

General Comment:

Environmental inspection related to Spill ID 459085, Spill ID 462238 and Pit Facility ID 109572. The pit was not maintaining 2 feet of freeboard and the COGCC EPS left a voicemail with the operator Friday (3/22/19) afternoon.

Inspected Facilities									
Facility ID:	109572	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	459085	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 109572Lat: 39.705472Long: -103.366270Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Pit berms appear to have been recently maintained. Pit not maintaining a minimum of two feet of freeboard in the northeast corner. A method of monitoring freeboard needs to be installed.

Corrective Action

Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 03/27/2019**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401985803	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4774448
688000285	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4774438